



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 28, 2013

Reviewed: 

Mine Name: Torrey Buff	Permit Number: S/055/0012
Operator Name: John Young	Inspection Date: 05/22/2013
Inspector(s): Wayne Western	Time:
Other Participants: none	Mine Status: INA
Weather Condition: 70's clear skies	Last Inspection: July 11, 2012
Bond Renewal Date: May 19, 2012	Bond Amount: \$10,000.00
Surface Ownership: SITLA/BLM	Mineral Ownership: SITLA
Last Year of Production: 2010	Acreage: 2 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The site has been reclaimed.

The bond is for \$10,000.00 – the Operator could file for a partial bond release.

There were no materials on site that posed an eminent environmental hazard.

Conclusions and Recommendations:

The Division should continue to monitor the site.

Inspection Date: May 22, 2013


Page 2 of 4

S/055/0012

The Division should ask the Operator if he wants to apply for a partial bond release.

Directions to Site:

Inspector's Signature

A handwritten signature in blue ink, appearing to read "Wayne Walter", is written over a horizontal line.

WHW:

cc: (OPERATOR)

John Blake, SITLA

O:\M055-Wayne\S0550012-YoungTorreyBuff\inspections\Insp05222013.doc



Southern area



Southern area in reclamation



Northern area



Northern area reclaimed.

May 28, 2013

Jon Young
2402 Broadview Court
Sandy, Utah 84092

Please
finalize
No task

Subject: Site Eligible for Bond Release, Jon Young, Torrey Buff Quarry, S/055/0012, Wayne County, Utah

Dear Mr. Young:

The Division conducted a routine inspection of the Torrey Buff Quarry on May 22, 2013. The Division found that the site had been reclaimed and in stable condition.

You can apply for a partial bond release on the site. The Division currently holds \$10,000.00 in bond and potentially could release up to \$7,000.00. If you want to apply for bond release please fill out the forms at http://linux1.ogm.utah.gov/WebStuff/wwwroot/minerals/permit_forms.html

Please call me at (801) 538-5261 or Wayne Western at (801) 538-5263.

Sincerely,

Paul Baker
Minerals Mining Manager
Minerals Regulatory Program

PB:whw:eb
Enclosure:
Attachment:
cc:
O:\M055-Wayne\S0550012-YoungTorreyBuff\draft\LTR-05282013.doc